कोलकाता पत्तन न्यास H.M.(R)'S OFFICE DIAMOND HARBOUR NOVEMBER'2018 Dated : 24.09.2018

ESTMATED FRESH WATER DRAFT FORECAST FOR THE MONTH OF NOV'2018 FOR DIAMOND HARBOUR FOR VESSELS OF 12KTS. & OVER (SUBJECT TO ALTERATION)

	DIAMONI	D HARBOL	JR FOR VE	SSELS OF 12KTS. & OVER (SUBJECT TO ALTERATION)
INWARD:				NOTES
Date	A 7.4	B 7.6	C 7.0	4. Coloulated for 40 lita Divar annual Industrial Dooft to be reduced
1st	7.4	7.6 7.8	7.8	1. Calculated for 12 kts River speed. Indward Draft to be reduced
*2nd 3rd	7.6 7.8	8.0	8.0 8.2	by 0.1 mtr for every knot below 12 kts. Outward draft to be reduced by 0.2 mtr for every knot below 12 knots.
4th	8.1	8.3	8.5	Toed by 0.2 Inti for every knot below 12 knots.
5th	8.3	8.5	8.7	
6th	8.3	8.5	8.7	2. LOA Category:
7th	8.3	8.5	8.7	A) Above 180 mtrs to 200 mtrs
8th	8.3	8.5	8.7	B) 160 mtrs to 180 mtrs.
9th	8.2	8.4	8.6	C) Below 160 mtrs.
10th	8.1	8.3	8.5	,
11th	8.0	8.2	8.4	3.a) Maximum size of vessel up to LOA 200 mtrs.
12th	7.8	8.0	8.2	b) Maximum permissible draft up to 9.5 mtrs.
13th	7.6	7.8	8.0	
14th	7.4	7.6	7.8	4. As there is no anchorage between Sagar and Diamond Harbour/
15th	7.2	7.4	7.6	Kulpi, all vessels to ensure that their engines and steering etc. are
16th	7.0	7.2	7.4	in good working order.
*17th	7.3	7.5	7.7	
18th 19th	7.4 7.6	7.6 7.8	7.8 8.0	5. All vessels are required to have two serviceable bower anchors.
20th	7.8	8.0	8.0	In view of strong tides at anchorage, Masters to ensure that the
20th	8.0	8.2	8.4	anchor chains, windlass etc. are in good working order.
22nd	8.2	8.4	8.6	anono onamo, windiaoo oto. are in good working older.
23rd	8.3	8.5	8.7	6. A.I.S. Pilot plug of all vessels are required to be oprational.
24th	8.3	8.5	8.7	
25th	8.3	8.5	8.7	7. Based on L.Silver Tree - 4.5 mtrs. & L.Maragolia - 5.1 mtrs.
26th	8.2	8.4	8.6	j
27th	8.0	8.2	8.4	8. Maximum of three vessels may be accommodated at ancho-
28th	7.7	7.9	8.1	rage subject to tidal/weather conditions. In strong tides/adverse
29th	7.5	7.7	7.9	weather or for any other reason, number of vessels at anchorage
30th	7.4	7.6	7.8	may be reduced.
OUTWARD				C Ferrando Historia Manetana
1st	7.3	7.5	7.7	Forecast subject to alterations.
2nd	7.4	7.6	7.7	10. Pilot embarkation at Middleton Channel. Time to be confirmed
3rd	7.5	7.7	7.9	from Sagar Pilot/VTS Station.
4th	7.6	7.8	8.0	
*5th	7.6	7.8	8.0	11. Inward vesels should report their ETA Sandheads to Pilot
6th	7.6	7.8	8.0	Station and ask for pilotage instructions between ECLV (21*04'N,
7th	7.6	7.8	8.0	88*11'12"E) and Gasper Channel before proceeding up.
8th	7.6	7.8	8.0	
9th	7.5	7.7	7.9	12. Assistance is available from VTMS Station at Haldia/Sagar
10th	7.5	7.7	7.9	on VHF Channel 16/68 above Lower Gasper Light Vessel.
11th	7.4	7.6	7.8	
12th	7.4	7.6	7.8	13. Inward Vessels anchoring at Sandheads to keep clear the
13th	7.4	7.6	7.8	shipping lane.
14th 15th	7.3 7.1	7.5 7.3	7.7 7.5	14. Masters to procure River Hugli Estuary Chart through their
16th	7.1	7.2	7.4	Agents from Chief Hydrographer, KoPT.
17th	7.1	7.3	7.5	- 35 Since the argument of the
18th	7.4	7.6	7.8	15. Proper anchor watch & VHF watch on Channel 16 to be
19th	7.5	7.7	7.9	maintained and M/E to be kept on short notice at the anchorage.
*20th	7.4	7.6	7.8	,
21st	7.4	7.6	7.8	
22nd	7.5	7.7	7.9	
23rd	7.5	7.7	7.9	
24th	7.5	7.7	7.9	<u>.</u>
25th	7.5	7.7	7.9	Sd/-
26th	7.5	7.7	7.9	
27th	7.4	7.6	7.8	HARBOUR MASTER(RIVER)
28th	7.4	7.6	7.8	बंदरगाह मास्टर (नदी)
29th	7.3	7.5	7.7	
30th	7.3	7.5	7.7	