

NOTICE

No.MRN/HMR/99/10

Dated : 16/04/2019

Distribution to All Concerned,

Reference Draft forecast No.MRN/HMR/DH/116 datd 15/02/2019, the inward/outward draft of Diamond Harbour for the month of **APRIL'2019** is **Revised** for remaining days is as follows :

KOLKATA PORT TRUST			
MRN/HMR/DH/116		কোলকাতা পত্তন ন্যাস DIAMOND HARBOUR APRIL'2019	
Dated:16/04/19			
ESTIMATED FRESH WATER DRAFT FORECAST FOR THE MONTH OF MAY'2019 FOR DIAMOND HARBOUR FOR VESSELS OF 12KTS. & OVER (SUBJECT TO ALTERATION)			
INWARD:			
Date	A	B	C
16th	7.7	7.9	8.1
17th	8.1	8.3	8.5
18th	8.3	8.5	8.7
19th	8.4	8.6	8.8
20th	8.5	8.7	8.9
21st	8.4	8.6	8.8
22nd	8.3	8.5	8.7
23rd	8.1	8.3	8.5
24th	7.9	8.1	8.3
25th	7.6	7.8	8.0
26th	7.4	7.6	7.8
27th	7.1	7.3	7.5
*28th	6.8	7.0	7.2
29th	6.9	7.1	7.3
30th	7.2	7.4	7.6
OUTWARD			
*16th	7.3	7.5	7.7
17th	7.4	7.6	7.8
18th	7.6	7.8	8.0
19th	7.7	7.9	8.1
20th	7.7	7.9	8.1
21st	7.7	7.9	8.1
22nd	7.7	7.9	8.1
23rd	7.6	7.8	8.0
24th	7.5	7.7	7.9
25th	7.4	7.6	7.8
26th	7.3	7.5	7.7
27th	7.1	7.3	7.5
28th	7.1	7.3	7.5
29th	7.2	7.4	7.6
30th	7.3	7.5	7.7
1. Calculated for 12 kts River speed. Inward Draft to be reduced by 0.1 mtr for every knot below 12 kts. Outward draft to be reduced by 0.2 mtr for every knot below 12 knots.			
2. LOA Category : A) Above 180 mtrs to 200 mtrs.. B) 160 mtrs to 180 mtrs. C) Below 160 mtrs.			
3.a) Maximum size of vessel up to LOA 200 mtrs. b) Maximum permissible draft up to 9.5 mtrs.			
4. As there is no anchorage between Sagar and Diamond Harbour/ Kulpi, all vessels to ensure that their engines and steering etc. are in good working order.			
5. All vessels are required to have two serviceable bower anchors. In view of strong tides at anchorage, Masters to ensure that the anchor chains, windlass etc. are in good working order.			
6. A.I.S. Pilot plug of all vessels are required to be operational.			
7. Based on L.Silver Tree - 4.6mtrs. (NEW) & L.Maragolia - 5.2 mtrs.			
8. Maximum of three vessels may be accommodated at anchorage subject to tidal/weather conditions. In strong tides/adverse weather or for any other reason, number of vessels at anchorage may be reduced.			
9. Forecast subject to alterations.			
10. Pilot embarkation at Middleton Channel. Time to be confirmed from Sagar Pilot/VTS Station.			
11. Inward vesels should report their ETA Sandheads to Pilot Station and ask for pilotage instructions between ECLV (21°04'N, 88°11'12"E) and Gasper Channel before proceeding up.			
12. Assistance is available from VTMS Station at Haldia/Sagar on VHF Channel 16/68 above Lower Gasper Light Vessel.			
13. Inward Vessels anchoring at Sandheads to keep clear the shipping lane.			
14. Masters to procure River Hugli Estuary Chart through their Agents from Chief Hydrographer, KoPT.			
15. Proper anchor watch & VHF watch on Channel 16 to be maintained and M/E to be kept on short notice at the anchorage.			
HARBOUR MASTER(RIVER)			

*Note : Lower Silver Tree bar is changed : actual 4.3 and revised 4.6