## S.M.P. KOLKATA

एस.एम.पी. कोलकाता

H.M.(R)'S OFFICE Dated: 26.07.2021

DIAMOND HARBOUR SEPTEMBER'2021 Dated: 26.07.20
ESTMATED FRESH WATER DRAFT FORECAST FOR THE MONTH OF SEPT'2021 FOR DIAMOND HARBOUR FOR VESSELS OF 12KTS. & OVER (SUBJECT TO ALTERATION)

INWARD:	DIAMIC	ND HARB	OUR FUR	NOTES
Date	Α	В	С	NOTES
*1st	7.6	7.8	8.0	Calculated for 12 kts River speed. Indward Draft to be reduced
2nd	7.7	7.9	8.1	by 0.1 mtr for every knot below 12 kts. Outward draft to be redu-
3rd	8.0	8.2	8.4	ced by 0.2 mtr for every knot below 12 kts. Outward draft to be redu-
4th	8.2	8.4	8.6	Total by 0.2 Intri for every knot below 12 knots.
5th	8.4	8.6	8.8	
6th	8.5	8.7	8.9	2 LOA Catagory
7th	8.7	8.9	9.1	LOA Category:     A) Above 180 mtrs to 200 mtrs
8th	8.7	8.9	9.1	B) 160 mtrs to 180 mtrs.
9th	8.7	8.9	9.1	C) Below 160 mtrs.
10th	8.6	8.8	9.0	C) Delow 100 miles.
11th	8.4	8.6	8.8	3.a) Maximum size of vessel up to LOA 200 mtrs.
12th	8.2	8.4	8.6	b) Maximum permissible draft up to 9.5 mtrs.
13th	8.0	8.2	8.4	b) Maximum permissible drait up to 9.5 milis.
14th	7.7	7.9	8.1	4. As there is no anchorage between Sagar and Diamond Harbour/
*15th	7.8	8.0	8.2	Kulpi, all vessels to ensure that their engines and steering etc. are
16th	7.8	8.1	8.3	in good working order.
17th	8.1	8.3	8.5	in good working order.
18th	8.3	8.5	8.7	
19th	8.5	8.7	8.9	5. All vessels are required to have two serviceable bower anchors.
20th	8.6	8.8	9.0	In view of strong tides at anchorage, Masters to ensure that the
21st	8.6	8.8	9.0	anchor chains, windlass etc. are in good working order.
-	8.5	8.7	8.9	janonoi onamo, windiaso etc. are in goda working oraer.
22nd 23rd	8.4	8.6	8.8	6. A.I.S. Pilot plug of all vessels are required to be oprational.
24th	8.3	8.5	8.7	o. Ali.o. I not plug of all vessels are required to be optational.
25th	8.2	8.4	8.6	7. Based on Bedford - 5.7mtrs. & L.Maragolia - 5.1 mtrs.
26th	8.1	8.3	8.5	7. Dased on Dediord - 5.7 miles. & E.Maragona - 5.1 miles.
27th	7.9	8.1	8.3	Maximum of three vessels may be accommodated at ancho-
28th	7.7	7.9	8.1	rage subject to tidal/weather conditions. In strong tides/adverse
29th	7.5	7.7	7.9	weather or for any other reason, number of vessels at anchorage
30th	7.3	7.5	7.7	may be reduced.
3011	7.0	7.0	7.1	9. Forecast subject to alterations.
OUTWARD				
1st	7.2	7.4	7.6	10. Pilot embarkation at Middleton Channel. Time to be confirmed
2nd	7.2	7.4	7.6	from Sagar Pilot/VTS Station.
3rd	7.3	7.5	7.7	l
4th	7.4	7.6	7.8	11. Inward vesels should report their ETA Sandheads to Pilot
*5th	7.7	7.9	8.1	Station and ask for pilotage instructions between ECLV (21*04'N,
6th	7.8	8.0	8.2	88*11'12"E) and Gasper Channel before proceeding up.
7th	7.8	8.0	8.2	
8th	7.8	8.0	8.2	12. Assistance is available from VTMS Station at Haldia/Sagar
9th	7.8	8.0	8.2	on VHF Channel 16/68 above Lower Gasper Light Vessel.
10th	7.8	8.0	8.2	
11th	7.7	7.9	8.1	13. Inward Vessels anchoring at Sandheads to keep clear the
12th	7.6	7.8	8.0	shipping lane.
13th	7.5	7.7	7.9	
14th	7.4	7.6	7.8	14. Master to check with Sagar VTS for any changes in the approach
15th	7.3	7.5	7.7	channel / way points to the Pilot Boarding Ground (PBG) before
16th	7.3	7.5	7.7	entering the channel.
17th	7.4	7.6	7.8	
18th	7.5	7.7	7.9	15. Proper anchor watch & VHF watch on Channel 16 to be
*19th	7.8	8.0	8.2	maintained and M/E to be kept on short notice at the anchorage.
20th	7.8	8.0	8.2	,
21st	7.8	8.0	8.2	
22nd	7.8	8.0	8.2	
23rd	7.7	7.9	8.1	
24th	7.6	7.8	8.0	
25th	7.6	7.8	8.0	
26th	7.5	7.7	7.9	Sd/-
27th	7.4	7.6	7.8	( D Sengupta )
28th	7.4	7.6	7.8	HARBOUR MASTER(RIVER)I/C
29th	7.3	7.5	7.7	बंदरगाह मास्टर (नदी) आई/सी
30th	7.2	7.4	7.6	
30111	1.2	1.4	ι.υ	
1				