## S.M.P. KOLKATA एस°एम°पी° कोलकाता

DIAMOND HARBOUR OCTOBER'2022

ESTMATED FRESH WATER DRAFT FORECAST FOR THE MONTH OF OCTOBER'2022 FOR DIAMOND HARBOUR FOR VESSELS OF 12KTS. & OVER (SUBJECT TO ALTERATION)

H.M.(R)'S OFFICE

Dated: 30.08.2022

	DIAMO	ND HARB	OUR FOR	VESSELS OF 12KTS. & OVER (SUBJECT TO ALTERATION)
INWARD:				NOTES
Date	A	В	С	
1st	7.9	8.1	8.3	1. Calculated for 12 kts River speed. Indward Draft to be reduced
2nd	7.7 7.4	7.9 7.6	8.1 7.8	by 0.1 mtr for every knot below 12 kts. Outward draft to be redu-
3rd *4th	7.4	7.8	8.0	ced by 0.2 mtr for every knot below 12 knots.
5th	7.7	7.8	8.1	
6th	8.0	8.2	8.4	2. LOA Category :
7th	8.2	8.4	8.6	A) Above 180 mtrs to 200 mtrs
8th	8.3	8.5	8.7	B) 160 mtrs to 180 mtrs.
9th	8.4	8.6	8.8	C) Below 160 mtrs.
10th	8.4	8.6	8.8	,
11th	8.3	8.5	8.7	3.a) Maximum size of vessel up to LOA 200 mtrs.
12th	8.2	8.4	8.6	b) Maximum permissible draft up to 9.5 mtrs.
13th	8.0	8.2	8.4	
14th	7.9	8.1	8.3	4. As there is no anchorage between Sagar and Diamond Harbour/
15th	7.7	7.9	8.1	Kulpi, all vessels to ensure that their engines and steering etc. are
16th	7.5	7.7	7.9	in good working order.
17th	7.3	7.5	7.7	
18th	7.1	7.3	7.5	- All
*19th	7.3	7.5 7.7	7.7 7.9	5. All vessels are required to have two serviceable bower anchors.
20th 21st	7.5 7.7	7.7	7.9 8.1	In view of strong tides at anchorage, Masters to ensure that the anchor chains, windlass etc. are in good working order.
21st 22nd	7.7	8.1	8.3	janonoi onams, windiass etc. are in good working order.
23rd	8.0	8.2	8.4	6. A.I.S. Pilot plug of all vessels are required to be oprational.
24th	8.1	8.3	8.5	10. A.r.o. I not plug of an vessels are required to be optational.
25th	8.2	8.4	8.6	7. Based on Bedford - 5.7mtrs. & L.Maragolia - 4.9 mtrs.
26th	8.3	8.5	8.7	g
27th	8.2	8.4	8.6	8. Maximum of three vessels may be accommodated at ancho-
28th	8.1	8.3	8.5	rage subject to tidal/weather conditions. In strong tides/adverse
29th	8.0	8.2	8.4	weather or for any other reason, number of vessels at anchorage
30th	7.7	7.9	8.1	may be reduced.
31st	7.5	7.7	7.9	9. Forecast subject to alterations.
OUTWA				
1st	7.3	7.5	7.7	10. Pilot embarkation at Middleton Channel. Time to be confirmed
2nd 3rd	7.2	7.4 7.3	7.6 7.5	from Sagar Pilot/VTS Station.
4th	7.1 7.0	7.3	7.3	11. Inward vesels should report their ETA Sandheads to Pilot
5th	7.1	7.3	7.5	Station and ask for pilotage instructions between ECLV (21*04'N,
6th	7.3	7.5	7.7	88*11'12"E) and Gasper Channel before proceeding up.
7th	7.4	7.6	7.8	Too 11 12 2) and caspor chainer scrote processaing up.
*8th	7.5	7.7	7.9	12. Assistance is available from VTMS Station at Haldia/Sagar
9th	7.6	7.8	8.0	on VHF Channel 16/68 above Lower Gasper Light Vessel.
10th	7.6	7.8	8.0	1
11th	7.5	7.7	7.9	13. Inward Vessels anchoring at Sandheads to keep clear the
12th	7.4	7.6	7.8	shipping lane.
13th	7.4	7.6	7.8	
14th	7.3	7.5	7.7	14. Master to check with Sagar VTS for any changes in the approach
15th	7.2	7.4	7.6	channel / way points to the Pilot Boarding Ground (PBG) before
16th	7.2	7.4	7.6	entering the channel.
17th	7.1	7.3	7.5	15 Drange angher watch & VUE watch on Channel 40 to be
18th 19th	7.0 7.0	7.2 7.2	7.4 7.4	15. Proper anchor watch & VHF watch on Channel 16 to be
20th	7.0	7.2	7.4	maintained and M/E to be kept on short notice at the anchorage.
21st	7.1	7.5	7.7	1
22nd	7.4	7.6	7.8	1
*23rd	7.4	7.6	7.8	1
24th	7.4	7.6	7.8	Sd/-
25th	7.4	7.6	7.8	( D Sengupta )
26th	7.4	7.6	7.8	HARBOUR MASTER(RIVER)I/C
27th	7.4	7.6	7.8	बंदरगाह मास्टर (नदी) आई/सी
28th	7.4	7.6	7.8	,
29th	7.3	7.5	7.7	
30th	7.2	7.4	7.6	1
31st	7.1	7.3	7.5	1
0.30	7.1	7.5	7.0	<u> </u>