



Syama Prasad Mookerjee Port, Kolkata
HALDIA DOCK COMPLEX
An ISO – 9001 : 2015 Organisation
Office of General Manager(Marine)
Jawahar Tower, Haldia Township
West Bengal, India PIN: –721607




No. GMM/084/EST/Trade Circular/898

Date: December 10, 2021

Trade Circular

SMPK, HDC has deployed 18 numbers pneumatic fenders to assist in shipping operation / double banking operations inside the impounded dock system. All vessel agents / representative of shipping lines are hereby advised to requisition for such pneumatic fenders wherever necessary. The charges for deployments of such fenders will be as per SOR of SMPK.

In case SMPK, HDC is not in a position to deploy the pneumatic fenders, the vessel agents / representation of shipping lines may deploy other suitable type of fenders subject to approval from Marine Operations Division.


(Capt. Abhijit Ghosh)
General Manager (Marine)-I/C
Haldia Dock Complex

Copy to GM(T)/GM (M&S)/GM (F) for information please.

Copy to Commandant, CISF for information & necessary action please.

Copy to MMOH / DMMOH / DDM for information & necessary action please.